

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5277	DATE	February. 9. 2023
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some vehicles with manual transmission were equipped with the peak torque limiter plastic housing which was low in strength due to its inappropriate molding conditions. For this reason, repeated clutch operations may result in damage to the housing, causing the clutch fluid to leak, and in the worst case, it may disable clutch operations to shift gears.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-JG3	「N-ONE」	2021	652
TOTAL			652