## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5281	DATE	February 15, 2023		
MANUFACTURER	SUZUKI MOTOR CORPORATION				
DESCRIPTION OF DEFECT	In the front brake master cylinder body, the fluid passage may remain closed due to improper setting of the passage for adjusting the brake fluid pressure. This can lead to more brake lever play under certain conditions, and in the worst case, braking distance may be longer.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SUZUKI	HAYABUSA	2022	1,557
		TOTAL	1,557