

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5290	DATE	February 27, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	If the directional switch of a motor grader is moved while the brake pedal is depressed and the directional switch is moved to the Forward before the vehicle stops, the pressure acting on the filter in the hydraulic circuit may exceed the allowable pressure due to insufficient examination of the peak pressure in the hydrostatic transmission. Accordingly, if the machine is used as it is, the filter may break. If it occurs, hydraulic oil leaks and the machine becomes unable to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-GD035	「GD405-7」	2019-2023	542
		TOTAL	542