

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5291	DATE	Feb. 28. 2023
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	During shipping inspections at a vehicle manufacturing plant, due to improper settings of the braking force inspection equipment for the parking brake system, the safety standard compliance of the braking force may not be properly confirmed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FC2ABA	[HINO Ranger]	2021~2022	21
2KG-FC2ABA			
2PG-FC2ABA			
2DG-FD2ABA		2021~2022	20
2KG-FD2ABA			
2KG-FD2ABG			
2PG-FD2ABA			
2PG-FD2ABG			
2DG-GC2ABA		2021~2022	49
2DG-GC2ABG			
2KG-GC2ABA			
2PG-GC2ABA			
2DG-GD2ABA		2021~2022	54
2KG-GD2ABA			
2KG-GD2ABG			
2PG-GD2ABA			
2PG-GD2ABG			
2KG-GX2ABA		2022	1
2PG-FS1AGA	[HINO Profia]	2021	3
2KG-FS1EGA		2021	3
2KG-FS1EJA		2018~2021	8
2PG-SH1AGGG		2021	1
2PG-SH1EDGG		2022	1
		TOTAL	161