

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5295	DATE	March 14, 2023
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In cylinder head of engine, the shape of the combustion chamber is out of tolerance due to the improper quality control of the mold. As a result, when gasoline fuel is used, an appropriate air-fuel ratio cannot be generated. In the worst case NOx may not be satisfied with Japanese exhaust emission standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBT-F198	「HG1F4F50D」	2022	1
		TOTAL	1