

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5294	DATE	Mar. 17. 2023
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain eligible units, during manufacturing stage an improper heat treatment process may have been applied to the lens of the turn signal lamp due to a parts control issue. As a result, the turn signal lamp lens may develop cracking and not meet the Japanese Act safety regulations for road vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BJ-BR125H	Z125 PRO	2021	2,817	
TOTAL			2,817	