

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5 3 0 6	DATE	April 3, 2023
MANUFACTURER	A T E X C O . , L T D .		
DESCRIPTION OF DEFECT	In noise suppression devices for wheel carriers, the exhaust pipe resonates at a specific engine speed due to improper study of the strength of the exhaust pipe mounting stay, and there are cases where the stay cracks. Therefore, if the pipe is continued to be used as it is, the cracks will progress, and in the worst case, the exhaust pipe may fall off while driving and interfere with other traffic.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S L 4 3	SL52	2022~2023	235
	SL57	2022~2023	251
		TOTAL	486