

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 0 8	DATE	April. 13. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the combination meter, a part of the memory of the graphic data may not be loaded because a part of the memory control program is inappropriate. Therefore, the meter may be displayed and hidden repeatedly at the next run, and the necessary information for driving such as speedometer and various warning lights may not be confirmed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-FE0	ARIYA	2 0 2 2	7 0 9
		TOTAL	7 0 9