

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5312	DATE	April 18, 2023
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	Insufficient strength of rear tire wheels which is for recall number R5284 may cause cracks. Therefore, if the forklift continues to be used as is, the rear tire wheel may be broken, and in the worst case, the tire may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB3F	FB35PXIII	2020 - 2021	3
		TOTAL	3