

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5311	DATE	2023/4/24
MANUFACTURER	MORITA CORPORATION 1-5, Techno Park, Sanda-shi, Hyogo, 669-1339, Japan		
DESCRIPTION OF DEFECT	For the propeller shaft of these Fire Fighting pump trucks, adoption parts without grease grooves in the universal joint part cause not being added sufficiently greased. As a result, the universal joint part may be damaged due to insufficient lubrication, and in the worst case, the propeller shaft may drop out, it will be impossible to drive the Fire Fighting pump truck. ※ No overseas production		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BF-TRY230	Toyota Dyna	2022~2023	52
TOTAL			52

(日本工業規格A列4番)