

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5315	DATE	Maye.11 2023
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some heavy-duty trucks, the CGW unit (Central GateWay unit, an ECU for exchanging signals) behind the air conditioning blower in the cab is installed at an inappropriate position, where moisture in the outside air taken into the blower case may seep out from the mating faces of the blower case and drip onto the connecter terminals of the CGW unit, resulting in corrosion or damage of the connecter terminals and the inner circuit board of the CGW unit. As a result, failures such as engine stopping while the vehicle is running, engine restart unable, malfunction of PTO, and non-functioning combination switch can occur.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FU70HY	「FUSO SUPER GREAT」	2021~2022	4
2KG-FU74HZ		2021~2022	51
2KG-FV70HY		2021~2022	91
2KG-FS70HZ		2021~2022	83
2KG-FS74HZ		2021~2022	127
2KG-FV70HZ		2021~2022	74
2KG-FV70HX		2018~2022	760
2KG-FV74HJR		2018~2022	79
2KG-FV70HZZ		2019~2022	36
2KG-FV70HYP		2019~2022	121
2KG-FV70GX		2017~2022	425
2KG-FV70HJR		2017~2022	785
2PG-FU75GZ		2017~2020	5
2PG-FY70GY		2017~2021	20
2PG-FY74GY		2017~2021	58
2PG-FS75HY		2019~2021	8
2PG-FP74GGR		2018~2021	36
2PG-FV70GZ		2017~2022	40
2PG-FU70HY		2017~2022	333
2PG-FV74HJR		2018~2022	81
2PG-FU74HY		2017~2022	240
2PG-FS75GY		2017~2022	7
2PG-FS74GY		2017~2022	19
2PG-FP74HGR		2021~2022	36
2PG-FU75HZ		2017~2022	1,125
2PG-FS75GZ		2017~2022	79
2PG-FS74GZ		2017~2022	421
2PG-FV74GZ		2017~2022	72
2PG-FV70GX		2017~2022	269

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS74HY	「FUSO SUPER GREAT」	2017～2022	202
2PG-FU74GY		2017～2022	152
2PG-FV70GY		2017～2022	138
2PG-FV70HZ		2017～2022	1,043
2PG-FS70HZ		2017～2022	1,066
2PG-FY74HY		2017～2022	349
2PG-FV70HY		2017～2022	939
2PG-FS75HZ		2017～2022	1,840
2PG-FU70GY		2017～2022	235
2PG-FU74GZ		2017～2022	418
2PG-FV74HZ		2017～2022	835
2PG-FY70HY		2017～2022	215
2PG-FP74HDR		2021～2022	525
2PG-FP74HER		2021～2022	194
2PG-FV70HX		2017～2022	3,969
2PG-FS74HZ		2017～2022	12,781
2PG-FU74HZ		2017～2022	5,031
2RG-FP74HGR		2017～2021	158
2RG-FP74HDR		2017～2021	2,462
2RG-FP74HER		2017～2021	1,069
		TOTAL	39,106