

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5319	DATE	May 11, 2023
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>The image processing of the navigation system may be interrupted when exposed to a heavy workload during its startup. Thus, when the user reverses the vehicle right after the system startup, the camera image may be temporarily interrupted.</p> <p>If the liquid crystal display does not display the camera image for checking the front and left side of the vehicle, the vehicle may not conform to Safety Regulations for Road Vehicles, Article 44 (Standard for Rear-View Mirror and similar devices).</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2021~2022	16,303
		TOTAL	16,303