

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5320	DATE	May 11, 2023
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to tightening without noticing the damage of an automatic tightening tool during production, some fixing bolts of rear brake calipers may not be tightened by specified torque value. These affected vehicles may not conform to Safety Regulations for Road Vehicles, Article 12 (install requirement in standard of braking device) .		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2022	74
		TOTAL	74