

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5318	DATE	May.15,2023
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some Aerial Work Platforms, clearance between the work platform and the rear axle torque rod may be narrow. Therefore, if the Aerial Work Platforms are continued to be used as it is, the work platform and the rear axle rod may contact with each other.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
2DG-FS1EHA	HINO 「HINO PROFIA」	2021 - 2022	10
		TOTAL	10