

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5325	DATE	May. 25. 2023
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the braking device, the front wheel brake hose is not assembled in the right place because of its inappropriate assembly to the vehicle body. For this reason, the hose is touching the end of the hose guide, which would damage the hose if this keeps being used as it is and may cause the brake fluid leakage to disable the front wheel brake in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BJ-JA61	「SUPERCUB 110PRO」	2022~2023	1,180
8BJ-JA62	「SUPERCUB 110MD」		740
		TOTAL	1,920