

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

|                       |   |      |            |
|-----------------------|---|------|------------|
| CAMPAIGN No.          |   | DATE | 1-Jun-2023 |
| MANUFACTURER          | KYOKUTO KAIHATSU KOGYO CO., LTD.<br>6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan  |      |            |
| DESCRIPTION OF DEFECT | In the discharging pump of the aluminum made tankers, the rigidity of the bracket for installing the pump and the bracket of the center bearing for connecting the drive shafts of the pump are insufficient due to the inadequate design consideration of the rigidity. Therefore, the pump or the drive shaft may fall off if those are being used as they are. |      |            |

| MANUFACTURER'S NAME | TYPE       | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------------------|------------|-----------------|---------------------|-------------------|
| HINO                | 2KG-FN1AJA | HINO PROFIA     | 2017~2022           | 83                |
|                     | 2PG-FN1AJA |                 | 2018~2021           | 28                |
|                     |            |                 | TOTAL               | 111               |