

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Export Vehicles

CAMPAIGN No.	5334	DATE	June. 9, 2023
MANUFACTURER	SHO – SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	In the parking brake of the agricultural chemical spraying vehicle, the manufacturing control of the hook and gear that holds the lever in a fixed state is inappropriate, so the strength of the hook and gear is insufficient, and the joint part may be worn and deformed. Therefore, if the vehicle is continued to be used as it is, the meshing becomes insufficient, and in the worst case, the parking brake may be released, making it impossible to park.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
H7	3S-V512	2018 – 2021	80
	3S-V522	2019 – 2021	110
G6	3S-C522	2019 – 2021	51
	3S-C522S	2019 – 2021	58
	SSA-G545	2019 – 2021	70
G9	3S-FS522PC	2019 – 2021	61
	SSA- α 522	2019 – 2021	85
EBT-J5	3S-CE642HC	2019 – 2021	106
	3S-FS642HC	2020 – 2021	35
J9	3S-C524P	2018 – 2021	110
	3S-C624P	2018 – 2021	159
	SSA-G565	2019 – 2021	50
YDM-J2	3S-FSE1052HC	2019 – 2021	136
	3S-CE1052HC	2019 – 2021	259
	SSA-G1020	2018 – 2020	120
YDN-K1	3S-FST1063H	2019 – 2020	43
G2	3S-FSE1052H	2021 – 2021	2
	3S-CE1052HC-TH	2021 – 2021	14
		TOTAL	1,549