

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5333	DATE	June 19. 2023
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>The strength of the front spindle of an agricultural tractor is insufficient due to improper evaluation at the design stage. Therefore, when the front weight and the front working machine are attached, the front spindle may crack due to repeated turning operations. If the tire is continued to be used as it is, in the worst case, the front spindle may break and the tire may fall off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YT490」	2015	22	Both wheel type and half crawler type
		2015	174	
		2015~2017	745	
-	「YT488A」	2017~2018	46	
-	「YT470」	2015~2018	234	Only half crawler type
	「YT463」	2015~2017	77	
TOTAL			1,298	