

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 2 6	DATE	Jul. 14. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the right headlight, due to improper setting of the optical axis adjustment equipment in the vehicle production plant. Therefore, the optical axis may conflict with regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6AA-FE13	NOTE AURA	2 0 2 2	6, 434
		TOTAL	6, 434