

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5354	DATE	July 14, 2023
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the fuel devices of internal-combustion engine forklift vehicles, because of improper design of fuel pipe for returning excessive fuel to tank, there are fuel pipes that may not fulfill enough strengths. In case of starting and stopping the engine repeatedly with current condition, there is a possibility that it may cause the fuel pipe to crack and lead to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A8FDL18	TOYOTA GENE0	2022	1
YDN-A8FDL25		2022	1
YDN-A8FDL30		2022	1
		TOTAL	3

Note) This recall campaign is submitted in purpose of adding number of vehicles involved on Campaign No. 5316, which is reported on April 26, 2023, since additional relevant vehicles have been newly found.