## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5357	DATE	Jul.27 2023	
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation			
DESCRIPTION OF DEFECT	2022, the exhaust control program v instructions for ren	On some vehicles subject to "Notification number 5109", dated March 3, 2022, the exhaust gas divergence prevention device control terminal (ACM) control program was not rewritten correctly due to inappropriate work instructions for remedial actions. As a result, the fault diagnosis of the ACM is not performed correctly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HX	「FUSO SUPER GREAT」	2019 <b>~</b> 2021	26
2KG-FV70HYP		2019 <b>~</b> 2021	5
2KG-FV70HZP		2019~2020	3
2PG-FS70HZ		2019 <b>~</b> 2021	28
2PG-FS74HZ		2019 <b>~</b> 2021	47
2PG-FS75HZ		2019~2019	2
2PG-FU70HY		2019 <b>~</b> 2021	3
2PG-FU74HZ		2019 <b>~</b> 2021	19
2PG-FV70HX		2019 <b>~</b> 2021	86
2PG-FV70HY		2019 <b>~</b> 2021	23
2PG-FV70HZ		2019 <b>~</b> 2020	29
		TOTAL	271