

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5361	DATE	August 3 ,2023
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In certain light-duty trucks, the control program of the dosing control unit (DCU) is inappropriate. Therefore, the operation of the malfunction indicator (MI) to illuminate/flash when the ignition key is turned on is not in accordance with the design intent, and fails to comply with the technical requirements for the on-board diagnostic system (for heavy-duty diesel vehicles J-OBDII) stated in Attachment 48, Article 41 of the Detailed Notification, Article 31 of the Safety Regulations for Road Vehicles.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NHR88A□ 2RG-NHR88AN	[ELF]	2022-2023	157
2RG-NHS88A□ 2RG-NHS88AN		2022-2023	94
2RG-NJR88A□ 2RG-NJR88AN□ 2RG-NJR88N		2022-2023	813
2RG-NJS88A□ 2RG-NJS88AN		2022-2023	145
2PG-NKR88R□ 2RG-NKR88A□ 2RG-NKR88AN□ 2RG-NKR88AR□ 2RG-NKR88N□ 2RG-NKR88R		2022-2023	577
2PG-NKS88A□ 2PG-NKS88AN□ 2RG-NKS88A□ 2RG-NKS88AN		2022-2023	164
2RG-NLR88AN□ 2RG-NLR88AR□ 2RG-NLR88N		2022-2023	713
2RG-NLS88AN□ 2RG-NLS88AR		2022-2023	92

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-NMR88R□ 2RG-NMR88AN□ 2RG-NMR88AR□ 2RG-NMR88N□ 2RG-NMR88R	[ELF]	2022-2023	731
2PG-NMS88AN□ 2RG-NMS88AN□ 2RG-NMS88AR		2022-2023	102
2RG-NNR88AN□ 2RG-NNR88AR		2022-2023	68
2RG-NNS88AN		2022-2023	5
2PG-NPR88AN□ 2PG-NPR88AR□ 2PG-NPR88N□ 2RG-NPR88AN□ 2RG-NPR88AR□ 2RG-NPR88N		2022-2023	2,348
2PG-NPS88AN□ 2PG-NPS88AR□ 2RG-NPS88AN□ 2RG-NPS88AR		2022-2023	128
		TOTAL	6,137