

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5364	DATE	August. 3. 2023
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	If an opening for discharging fuel evaporative emissions is located inappropriately on a fuel pump, it can prevent fuel evaporative emissions from being discharged when the vehicle is driving in an environment where atmospheric pressure is low due to a high altitude, etc., or in heavy traffic while ambient temperature is high, which may result in a large amount of the emissions retained within the fuel pump. This has the risk of difficult fuel supply, leading to an engine failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-PC40	「CBR600RR」	2020～2022	1,975
		TOTAL	1,975