

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5365	DATE	Aug 10, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	If the power supply voltage drops during the self-diagnosis of safety relay which is started automatically after the key is turned ON, self-diagnosis does not complete normally. Due to improper program in the work equipment controller of the wheel loaders. Even in this condition, the machine can travel and operate normally. However, the machine stops suddenly if the transmission wiring gets shorted while the machine is traveling.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA142	「WA470-10」	2019-2023	39
		TOTAL	39