

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5 3 6 7	DATE	21 Aug. 2023
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	<p>In some parking brake devices attached to travel transmissions of agricultural chemical spray vehicles, welding of pins attached to the back plate of the brake device is not reliable. Therefore, when the vehicle is driven with the parking brake applied, the welded portion of the pin may come off and the pin may fall off, leaving the parts inside the brake device free. The parking brake will not work. Also, if the vehicle continues to run in this state, the freed parts may get caught in the brake shaft and the vehicle may not be able to run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	SSA-E502DX	2021～2023	140
	SSA-E502DX-1		
	SSA-E542DX	2021～2023	253
	SSA-E542DX-1		
		TOTAL	393