

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 8 0	DATE	Sep. 28. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the inverter controlling the drive motor, the unnecessary abnormality determination of the drive motor may be performed due to inappropriate abnormality determination program of drive motor. Therefore, EV system warning message is displayed on the combination meter and the drive motor output is stopped, the vehicle may not be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-FE0	ARIYA	2021~2023	3,844
ZAA-SNFE0		2022~2023	1,180
		TOTAL	5,024