

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 8 1	DATE	Sep. 28. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the power network separate (PNS) relay that controls the circuit connection between the 12V battery and the 12V sub-battery, the evaluation in the control program for power supply voltage fluctuation was insufficient in development.</p> <p>If the power is turned on when the voltage of the 12V battery is low, the PNS relay may be turned off and power to the 12V sub-battery may not be supplied.</p> <p>Therefore, if continue to be driven on this condition, the voltage of the 12V sub-battery may be decreased, and the combination meter warning lamp is turned on, and finally once the vehicle is stopped, READY ON may not be possible again.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-FE0	ARIYA	2021~2022	2, 233
		TOTAL	2, 233