

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5382	DATE	Sep.28 2023
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some heavy-duty trucks, the tailpipe connected to the silencer is made of an inappropriate material. If the truck continues to be used with snow-melting agents, etc., remaining on the connection, the tailpipe may corrode and break at the connection, causing nearby air tubes to melt due to exhaust gas from the silencer outlet. In the worst case, a decrease or failure of braking force, sudden parking brake activation, or a transmission gear shift failure may occur. Furthermore, if the fixing clamps for the broken tailpipe break, the tailpipe may fall and affect the safety of other traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LDG-FV50VX	「FUSO SUPER GREAT」	2011~2012	333	
LDG-FV50VY		2011~2012	92	
LKG-FS50VZ		2011~2012	87	
LKG-FS54VY		2011~2012	9	
LKG-FS54VZ		2011~2012	440	
LKG-FS55VZ		2011~2012	82	
LKG-FU54VZ		2011~2012	44	
LKG-FU55VZ		2011~2012	11	
LKG-FV50VX		2011~2012	140	
LKG-FV54VZ		2011~2012	9	
QDG-FV50VX		2011~2012	135	
QDG-FV50VY		2011~2012	103	
QKG-FS50VZ		2011~2014	589	
QKG-FS54VY		2012~2014	115	
QKG-FS54VZ		2011~2014	4,314	
QKG-FS55VY		2012~2014	7	
QKG-FS55VZ		2012~2014	817	
QKG-FU54VY		2012~2014	28	
QKG-FU54VZ		2011~2012	6	
QKG-FU55VZ		2012	1	
QKG-FV50VX		2011~2014	5,578	
QKG-FV50VY		2012~2014	568	
QKG-FV54VZ		2012	1	
QKG-FV60VX		2014~2015	1,976	
QKG-FV60VY		2014~2015	199	
QPG-FS60VZ		2014~2015	191	
QPG-FS64VY		2014~2015	41	
QPG-FS64VZ		2014~2015	1,819	
QPG-FS65VZ		2014~2015	304	
QPG-FU64VY		2014~2015	23	
		TOTAL	18,062	