VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5376	DATE	Oct.12. 2023		
MANUFACTURER	SUBARU TECNICA INTERNATIONAL INC.				
DESCRIPTION OF DEFECT	Since length of mounting screws for the rear spoiler is not appropriate, the screws may loosen due to vibration during driving, etc. In the worst case, the spoiler may fall off.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
CBA-GVB	$\lceil \text{IMPREZA} \rfloor$	2012-2013		302
D B A - ZC6	$\lceil \mathrm{BRZ} floor$	2013~2014		141
C B A - VAB	「WRX」	2015~2016		200
DBA-VAG	「WRX」	2016~2017		312
		•	TOTAL	955