

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5395	DATE	October. 13. 2023
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump of field servicing may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

The affected parts shipped as repair parts, but the vehicles with them installed, can be identified.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JF2	「N BOX Custom」	2013	1
DBA-FK8	「CIVIC」	2018	1
TOTAL			2

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS "SERVICE PARTS"	NUMBER OF PARTS	NOTE
MODULE ASSY., FUEL PUMP	17045-TY0-J01	2017~2021	404	「N BOX」 「N-BOX」 「N BOX Custom」
	17045-TY5-000	2017~2020	202	「N-BOX Custom」 「N BOX +」 「N-BOX +」
	17045-TY5-J00	2017~2021	107	「N BOX + Custom」 「N-BOX + Custom」
	17045-TY6-000	2017~2020	23	「N-BOX SLASH」 「N ONE」 「N-ONE」
	17045-TY0-000	2017~2020	168	「N BOX」 「N-BOX」 「N BOX Custom」 「N-BOX Custom」
	17045-TY1-000		38	「N BOX +」 「N-BOX +」 「N BOX + Custom」 「N-BOX + Custom」 「N-BOX SLASH」

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS	NOTE
MODULE ASSY., FUEL PUMP	17045-T6H-010	2017~2020	161	「N BOX」 「N-BOX」 「N BOX Custom」 「N-BOX Custom」 「N BOX +」 「N-BOX +」 「N BOX + Custom」 「N-BOX + Custom」
	17045-T6K-000	2017~2021	42	「N-BOX SLASH」 「N ONE」 「N-ONE」 「N-WGN」 「N-WGN CUSTOM」
	17045-T6G-010	2017~2020	169	「N BOX」 「N-BOX」 「N BOX Custom」 「N-BOX Custom」 「N BOX +」 「N-BOX +」 「N BOX + Custom」 「N-BOX + Custom」 「N-BOX SLASH」 「N-WGN」 「N-WGN CUSTOM」
	17045-TTA-000	2017~2020	225	「N-BOX」 「N-BOX Custom」 「N-VAN」 「N-WGN」 「N-WGN Custom」
	17045-TTC-000		167	
	17045-TTB-000		59	
	17045-TTD-000		48	
	17045-T6J-000	2017~2020	31	「N-WGN」 「N-WGN CUSTOM」
	17045-T5A-000	2017~2020	348	「FIT」 「GRACE」 「SHUTTLE」
	17045-T5E-010		117	
	17045-T5B-000	2017~2020	135	「FIT」 「GRACE」 「SHUTTLE」 「VEZEL」
	17045-T5F-010		46	
	17045-TF0-J00	2017~2020	56	「FIT」 「FIT SHUTTLE」
	17045-TF2-J00		46	
	17045-TF2-J30	2017~2021	12	「FIT」

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS	NOTE
MODULE ASSY., FUEL PUMP	17045-TGH-G00	2017~2020	157	「CIVIC」
	17045-TBA-X00		42	
	17045-TED-T00		15	
	17045-TDK-010	2017~2020	57	「FREED」 「FREED+」
	17045-TDL-000		46	
	17045-TDN-000	2017~2021	37	
	17045-TDM-000	2017~2020	22	
	17045-TAA-003	2017~2020	92	「STEPWGN」
	17045-TAB-000	2017~2021	41	
	17045-TAD-003	2017~2020	23	
	17045-T6A-000	2017~2020	55	「ODYSSEY」
	17045-T6C-000		55	
	17045-T6B-000		12	
	17045-TY3-000	2017~2020	47	「LEGEND」
	17045-TMB-H00	2017~2020	22	「CR-V」
	17045-TLA-X01		18	
	17045-T0A-010	2017~2018	3	
	17045-T4R-020	2017~2020	21	「JADE」
	17045-T4P-000		12	
	17045-TDJ-000	2017~2020	31	「S660」
	17045-SZT-930	2017~2020	7	「CR-Z」
	17708-SJA-A51	2017~2019	5	「LEGEND」
	17045-TM9-931	2017~2021	5	「INSIGHT EXCLUSIVE」
	17045-TRW-A00	2017~2020	1	「CLARITY」
	17045-T6N-X01	2017~2018	1	「NSX」
				TOTAL