

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5 3 9 7	DATE	25 OCT. 2023
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In the operating device for changing the speed of agricultural chemical spraying vehicles, due to lack of lubricant to the parts in the operating device, when the operating device (HST lever) is returned to the neutral position, the HST lever tilts toward the forward side. The vehicle may not stop and cause an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	BSA-2000CH	2023	18
	BSA-2000CE	2023	5
	BSA-2000CHE	2023	9
		TOTAL	32