

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5 3 9 8	DATE	25 OCT. 2023
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In agricultural chemical spraying vehicles, the propeller shaft may become loose due to insufficient tightening torque of the fastening bolt. If the vehicle is used in this state, the propeller shaft may fall off and the vehicle may become unable to drive or control.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	BSA-2000CH	2023	18
	BSA-2000CE	2023	5
	BSA-2000CHE	2023	9
		TOTAL	32