

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5383	DATE	2023/11/17
MANUFACTURER	MORITA ECONOS CORPORATION 28 Techno Park, Sanda-shi, Hyogo, 669-1339, Japan		
DESCRIPTION OF DEFECT	In small rotary garbage truck, due to the improper wiring on the right side inside the high mount rear panel, the wire contact with rear door accessory when the rear door is opened and closed, and might disconnection. As a result, the turn signals and other lights in the rear of the vehicle may not work, or not meet safety standards because of the insufficient number of flashes, which could result in a serious accident in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZU700A	Toyota Dyna	2018~2019	3
TKG-XZU710		2016	1
2KG-XZU700M	Hino Dutro	2017~2021	49
2KG-XZU700X		2017~2021	55
2KG-XZU710M		2018~2021	21
2PG-XZU710M		2021	1
2SG-XKU702M		2019~2021	7
2SG-XKU712M		2019	1
TKG-XZU700M		2016~2020	16
TKG-XZU700X		2016~2017	15
TKG-XZU702M		2017~2019	5
TKG-XZU710M		2016~2017	2
TPG-XZU702M		2017~2019	2
TSG-XKU700M		2016~2017	4
TSG-XKU712M		2018	1
TKG-FC9JCAA		Hino Ranger	2017
2PG-NPR88AN	Isuzu Elf	2020	2
2PG-NPR88YN		2018~2021	121
2RG-NPR88YN		2018~2021	45
TFG-NPR82ZN		2018	4
TKG-NPR85YN		2016~2018	63
TPG-NPR85AN		2016~2019	13
TPG-NPR85N		2018	6
TPG-NPR85YN		2016~2017	3
2PG-FRR90S2	Isuzu Forward	2018~2020	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FEB50	Mitsubishi Fuso Truck and Bus Canter	2020	1
2PG-FEB90		2017~2021	89
2RG-FEB50		2021	1
2RG-FEB90		2018	4
TKG-FEB90		2016~2017	17
TPG-FEB80		2019	2
TPG-FEB90		2016~2017	21
2PG-FEB9Y		UD Trucks Kazet	2019~2021
		TOTAL	582

(日本工業規格A列4番)