

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5411	DATE	Nov.21,2023
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	Mounting position of rear reflectors in rear combination lamps do not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
2PG-FD2ABA	HINO 「HINO RANGER」	2022 - 2023	2
		TOTAL	2