

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5415	DATE	Nov.21 2023
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty trucks and buses equipped with a manual transmission, a defective backup light switch is installed. If the vehicle continues to be used in this condition, it may not be able to correctly detect the state when reversing. Accordingly, the backup lights may not come on and the backup buzzer may not sound when the gear is shifted to reverse.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FEA80	「FUSO CANTER」	2021~2022	4	
2PG-FEB80		2021~2022	254	
2PG-FEB90		2021~2022	382	
2PG-FEBM0		2021~2022	55	
2PG-FEC90		2022~2022	5	
2PG-FED90		2021~2022	32	
2RG-FBA20		2021~2022	1,054	
2RG-FBA30		2021~2022	342	
2RG-FBA60		2021~2022	1,304	
2RG-FBAV0		2021~2022	308	
2RG-FEA20		2021~2022	65	
2RG-FEA80		2021	1	
2RG-FEAV0		2021~2022	402	
2RG-FEB20		2021	1	
2RG-FEB50		2021~2022	486	
2RG-FEB80		2021~2022	225	
2TG-FBA00		2022~2022	2	
2RG-BE740E		「FUSO ROSA」	2021~2022	13
2RG-BE740G			2021~2021	38
2RG-BE740J	2021~2022		10	
2PG-FEB9Y	「Kazet」	2021~2022	6	
2PG-FEC9Y		2021	1	
2RG-FBA2Y		2021	1	
2RG-FBA6Y		2022~2022	4	
2RG-FBAVY		2021~2022	3	
2RG-FEAVY		2021	1	
2RG-FEB5Y		2021~2022	4	
2RG-FEB8Y		2021~2022	4	
		TOTAL	5,007	

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS No.	SHIPMENT YEAR	NUMBER OF PARTS	REMARKS
MANUAL TRANSMISSION Assy	M038S6	2021~2022	9	
BACK LAMP SWITCH	ME530404		31	
		TOTAL	40	