

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5418	DATE	November 22 ,2023
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy-duty and medium-duty sightseeing buses, due to inappropriate installation instructions for onboard tools, a parking brake release tool (spanner)is not installed. Therefore, if the parking brake remains operated due to a malfunction, etc., the brake cannot be released using the tool.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-RU1ASDJ	[ISUZU GALA]	2017-2023	892
2KG-RU1ESDJ□ 2PG-RU1ESDJ		2017-2022	493
2DG-RU2AHDJ□ 2KG-RU2AHDJ		2017-2023	249
2DG-RR2AJDJ	[ISUZU GALA MIO]	2017-2023	786
		TOTAL	2,420