

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5421	DATE	Nov 24, 2023
MANUFACTURER	AZAPA		
DESCRIPTION OF DEFECT	In a vehicle converted to an electric vehicle, improper control of the control unit at high speed rotation of the electric motor may cause the fail function of the control unit to be activated during re-acceleration while driving at high speed, resulting in loss of driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA350S	Mira e:s	2023	14
		TOTAL	14