

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 4 1 4	DATE	November30.2023
MANUFACTURER	NICHIJO CORPORATION		
DESCRIPTION OF DEFECT	In the lights of antifreeze spray trucks, water sprinklers, and rotary snowplows, Due to insufficient legal checks when setting options, the color of the light reflected from the rear sign board was white, which did not meet safety standards.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FS1EPYA	Hino Profile	2007 FS1EPY-10303~FS1EPY-10350	6
BDG-FX7JGWA	Hino Ranger	2007 FX7JGW-10054	1
2DG-CF5AL	Quon	2018 JNCMBNOB2JU037131	1
2PG-FTS90S2	Forward	2017~2018 FTS90-7000008~FTS90-7000030	9
YDS-R03F	HTR308A	2019 R03F-0078	1
YDR-R08E	HTR148	2020 R08E-0040	1
		TOTAL	19

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.