

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5408	DATE	04 December 2023
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	At the Shovel loader, due to improper structure of fuel pipe, vibration apply an excessive stress, and it may cause fuel leakage.become In the worst case scenario, if leaked fuel adheres to hot parts, it may lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDP-H88	「ZW100-6」	2020~2022	899	
YDP-H87	「ZW120-6」	2020~2022	125	
YDP-8SDT21	「8SDT21」	2020~2022	4	
		TOTAL	1028	