

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5426	DATE	December. 13. 2023
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The inadequate circuit of a battery cable connecting the sub-fuse box to the battery of a hybrid vehicle may cause the cable to keep carrying current if another vehicle crashed into the vehicle and the cable was damaged and short-circuited due to the impact of the side collision. Then, the cable may produce heat by the short circuit current and, in the worst case, there is a risk of fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-RT5	「CR-V」	2018~2022	11,310
6AA-RT6			8,973
		TOTAL	20,283