

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5461	DATE	Mar. 7 2024
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some medium-duty trucks with two rear drive axles, the oil lubrication structure for the inter- differential attached rear-front axle is inappropriate, causing the rear-front axle differential oil to become excessively hot during driving and the pressure inside the rear-front axle to increase. As a result, oil may leak from the air breathers or oil seals.</p> <p>Additionally, excessively high differential oil temperatures can cause early oil deterioration, accelerating wear of the bearings and gears in the inter-differential and rear-front axle differentials, causing abnormal noise.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-FQ62F	「FUSO FIGHTER」	2016～2017	307
2DG-FQ62F		2017～2021	1,344
		TOTAL	1,651