

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5462	DATE	March 14, 2024
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to an inappropriate control program in the navigation system, when the navigation is started, information processing in the system may not complete and the navigation may keep rebooting. Therefore, the images from the camera to check the area in front and to the left side of a vehicle are not displayed on the liquid crystal screen, and this may not conform to Safety Regulations for Road Vehicles, Article 44 (Standard for Rear-View Mirror and similar devices).		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2021～2022	102
		TOTAL	102