

# VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5469	DATE	Apr.5,2024
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	On some cranes, tightening torque for seat adjuster fixing bolts on the seat may be insufficient. Therefore, if the crane is continued to be used as it is, the bolts may be removed and the seat rattle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
TADANO	「GR-250N-5」	2023 - 2024	183
TADANO	「GR-700N-2」 「GR-1000N-1」	2023 - 2024	121
TADANO	「GR-600N-3」	2023 - 2024	35
TADANO	「eGR-250N-1」	2024	1
KOBELCO	「RK700-3」	2023 - 2024	2
		TOTAL	342