

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5 4 7 0	DATE	April 10, 2024
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	In some agricultural tractor running devices, the coating on the wheel is insufficient hardness due to improper coating process. Therefore, there is a risk that the wheel bolts and nuts become loose.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	RTS255	2023	1
—	RTS205	2023	3
—	RTS225	2023	1
—	BF32	2023	2
—	BF29	2023	1
		TOTAL	8