

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN  
Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	5 4 7 6	DATE	May. 17. 2024
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	Due to improper work instructions and checks at the fastening area (front) between the chassis and body of van-type trucks, etc., the back plate that fixes the fastening parts (bracket mounts) may pinch the brake piping of the truck chassis. As a result, in the worst case, there is a possibility of unilateral braking during brake operation.		

TYPE		COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ISUZU	2RG-FRR90S2	FORWARD	2022-2023	21
ISUZU	2RG-FRR90T2	FORWARD	2023	5
UD TRUCKS	2PG-BRR90S1	CONDOR	2022	1
			Total	27