

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 4 8 3	DATE	May. 30. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the navigation controller, the navigation system may not operate normally due to an inappropriate control program. Therefore, the camera images for confirming the immediate front and left side of the vehicle may not be displayed.</p> <p>Additionally, some vehicle models have inappropriate control program in the communication control device (CAN gateway) between the in-vehicle control units, and if an abnormality in the navigation system is detected, the engine/e-POWER system may not be able to start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-FE0	ARIYA	2021~2023	8, 186
ZAA-SNFE0		2022~2023	2, 959
6AA-GFC28	SERENA	2023	22, 896
6AA-GC28			1, 181
5BA-FC28		2022~2023	17, 492
5BA-FNC28		2023	3, 945
5BA-C28		2022~2023	977
5BA-NC28		2023	263
6AA-SNT33		X-TRAIL	2022~2023
6AA-T33	2022~2023		2, 273
		TOTAL	85, 845