

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 4 8 4	DATE	May. 30. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In a communication control device (CAN gateway) between vehicle-mounted control units, communication failure of the vehicle-mounted control unit may occur due to improper control program. As a result, the warning light may illuminate during operation, and the driver assistance system may not operate, or it may lead to a failure to start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-GFC 2 8	S E R E N A	2 0 2 3~2 0 2 4	4 5, 3 2 0
6 AA-GC 2 8		2 0 2 3	5, 1 2 0
5 BA-FC 2 8		2 0 2 2~2 0 2 4	2 6, 1 0 8
5 BA-FNC 2 8		2 0 2 3~2 0 2 4	5, 7 5 7
5 BA-C 2 8		2 0 2 2~2 0 2 3	6, 1 8 6
5 BA-NC 2 8		2 0 2 3	1, 8 2 2
		TOTAL	9 0, 3 1 3