

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5486	DATE	Jun 6, 2024
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In forklift trucks, due to improper machining, steering axle dimensions may be incorrect. If the steering wheel is turned to the left to the maximum steering angle, the left rear wheel may interfere with the steering axle. (Violation of the Safety Regulations for Road Vehicles in Japan.)		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDR-F190	「FD70-4」	2021	4
YDR-F191	「FD80-4」	2021 - 2022	6
YDR-F192	「FD100-4」	2021 – 2022	5
YDR-F193	「FD60-4L」 「FD70-4L」	2021	2
		TOTAL	17