

# VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5492	DATE	Jun. 6 , 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The amount of the activated carbon packed in the fuel vapor emission control device (canister) may be insufficient, due to the improper design of the canister case. The canister case may also deform while the vehicle is in use.</p> <p>Due to the above, activated carbon void may be created in the canister, resulting in the performance deterioration of the canister that may cause the vehicle does not comply with the Article 31 of the safety/emission standards (Device for preventing emission of harmful gas).</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
5AA-YEH1S	ESCUDO	2022~2024	3,326	
		TOTAL	3,326	