

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5488	DATE	July 1 , 2024
MANUFACTURER	Hino Motors,Ltd. Isuzu Motors,Ltd Mitsubishi Motors,Ltd UD Trucks Corp. FURUKAWA UNIC CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing instructions and management, some of the caps attached to both ends of the intrusion prevention device have a radius of curvature of less than 2.5 mm. Therefore, it does not meet the standards for intrusion prevention devices (UNR58).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FSR90	Isuzu Forward	2021	97
2PG-FTR90		2021	1
2RG-FTR90		2021	34
2RG-FRR90		2021	16
2PG-FSR90		2021	2
2PG-FE2AB	Hino Ranger	2021	12
2PG-FE2AC		2022	30
2PG-FJ2AB		2021	3
2KG-FJ2AB		2021	1
2KG-FJ2AC		2022	2
2PG-FJ2AC		2022	11
2KG-GC2AB		2021	1
2KG-FC2AB		2021	4
2PG-FD2AB		2021	21
2KG-FD2AB		2021	18
2DG-GC2AB		2021	3
2KG-GC2AB		2021	16
2PG-GC2AB		2021	18
2KG-GD2AB		2022	9
2PG-GD2AB		2021	20
2DG-FC2AB		2021	1
2PG-FC2AB		2023	3
2KG-GX2AB		2021	2

第4号様式(英文リコール概要書) (第2関係)

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FK62F	Mitsubishi Fighter	2021	11
2KG-FK65F		2021	3
2KG-FK72F		2022	10
2KG-FK62FY		2021	27
2KG-FK65FY		2022	4
2KG-FK72FY		2021	36
2KG-FK62FZ		2021	211
2KG-FK65FZ		2021	7
2KG-FK72FZ		2022	5
2PG-FK72NA		2022	1
2KG-FK75F		2022	1
2PG-BSR90	UD Trucks Condor	2023	1
2PG-BRR90		2023	1
2RG-BRR90		2021	1
2RG-BSR90		2022	1
		TOTAL	645